**Location:** B & J CONVENIENCE STORE **Sys Fac ID:** 56-13910

US HIGHWAY 212 Last Inspected On: 5/18/2015

ALZADA, MT 59311 CARTER Operating Permit Renewal Date: 9/17/2018

Contact: Bill Walker, (406) 828-4400

Owners/Operators: William Walker, Owner (406)-828-4400 PO BOX 74

ALZADA MT 59311-0074

William Walker, UST Class A Operator Janet Walker, UST Class B Global Operator

Tank Id Tag Number Status Product Capacity	Age AST		Tank Material of Construction Secondary Option Catastrophic L.D. Type 3.0 Tank Detection ATG Type	Piping Material Secondary Option Piping Type Primary Pipe Detection Secondary Pipe Detection	Overfill Types Spill Protected CP Met Types Vapor Recovery Energy Act						
						1	17	12/1/1998	Steel Clad	Flexible Plastic	Flapper Valve (Auto Shutoff)
						3564			Double-Walled	None	Yes
						Currently in Use			Not Required	Safe Suction	Not Applicable
						Gasoline			Manual Interstitial Monitor	Deferred	
8,000											
2	17	12/1/1998	Steel Clad	Flexible Plastic	Flapper Valve (Auto Shutoff)						
3565			Double-Walled	None	Yes						
Currently in Use			Not Required	Safe Suction	Not Applicable						
Diesel			Manual Interstitial Monitor	Deferred							
4,000											

Report Generation Date: 2/29/2016 Page 1

Location: HOSPITAL COURTHOUSE Sys Fac ID: 06-00863

101 PARK ST Last Inspected On: 7/28/2015

EKALAKA, MT 59324 CARTER Operating Permit Renewal Date: 8/3/2018

Contact: Edward McBride, (406) 775-8749

(406)-775-6298 PO BOX 315 EKALAKA MT 59324-0315

Robert D. Jacobs, UST Class A Operator

Robert D. Jacobs, UST Class A Operator

Robert D. Jacobs, UST Class B Global Operator

Age Installed Tank Materia

Owners/Operators: Carter County, Owner

Tank ld	Age	Installed	Tank Material of Construction	Piping Material	Overfill Types
Tag Number	AST	Sump Tightness	Secondary Option	Secondary Option	Spill Protected
Status		Inventory Control	Catastrophic L.D. Type 3.0	Piping Type	CP Met Types
Product		Tank/Pipe CP	Tank Detection	Primary Pipe Detection	Vapor Recovery
Capacity		Line Tightness	ATG Type	Secondary Pipe Detection	Energy Act
2	24	7/1/1991	Cathodically Protected Steel	Steel	Flapper Valve (Auto Shutoff)
532			Double-Walled	none	Yes
Currently in Use			Not Required	U.S. Suction	Impressed Current
Heating Oil		7/28/2015	Manual Interstitial Monitor	Manual Interstitial Monitor	
6,000					

Report Generation Date: 2/29/2016 Page 2

FRUIT SERVICE & REPAIR INC MAIN ST **Sys Fac ID:** 06-01681 Location:

40 MAIN ST

Last Inspected On: 7/28/2015 CARTER

EKALAKA, MT 59324 **Operating Permit Renewal Date:** 8/17/2018 Troy Fruit, (406) 775-6541 Contact:

Owners/Operators: Fruit Service & Repair Inc, Owner PO BOX 318 (406)-775-6541

EKALAKA MT 59324-0318

Troy Fruit, UST Class A Operator Mikel Fruit, UST Class B Operator

Tank Id	Age	Installed	Tank Material of Construction	Piping Material	Overfill Types						
Tag Number Status Product Capacity	AST	Sump Tightness Inventory Control Tank/Pipe CP Line Tightness	Secondary Option	Secondary Option Piping Type Primary Pipe Detection Secondary Pipe Detection	Spill Protected CP Met Types Vapor Recovery Energy Act						
						3	25	4/26/1990	Steel Clad	Fiberglass Reinforced Plastic	Flapper Valve (Auto Shutoff)
						1132			Double-Walled	None	Yes
						Currently in Use			Not Required	Safe Suction	Not Applicable
Gasoline			Continuous Interstitial Monitor	Deferred							
1,000											
4	25	4/26/1990	Steel Clad	Fiberglass Reinforced Plastic	Flapper Valve (Auto Shutoff)						
1133			Double-Walled	None	Yes						
Currently in Use			Not Required	Safe Suction	Not Applicable						
Gasoline			Continuous Interstitial Monitor	Deferred							
1,000											
5	25	4/26/1990	Steel Clad	Fiberglass Reinforced Plastic	Flapper Valve (Auto Shutoff)						
1134			Double-Walled	None	Yes						
Currently in Use			Not Required	Safe Suction	Not Applicable						
Diesel			Continuous Interstitial Monitor	Deferred							
1,000											

Report Generation Date: 2/29/2016 Page 3

FRUIT SERVICE & REPAIR INC SR 323 **Sys Fac ID:** 06-03234 Location:

31 MT HIGHWAY 323

Last Inspected On: 7/28/2015 **Operating Permit Renewal Date:** 8/17/2018 EKALAKA, MT 59324 **CARTER** 

Troy Fruit, (406) 775-6541 Contact:

Owners/Operators: Fruit Service & Repair Inc, Owner

PO BOX 318 (406)-775-6541

EKALAKA MT 59324-0318

Troy Fruit, UST Class A Operator Dana Blutt, UST Class B Operator Mikel Fruit, UST Class B Operator

Tank Id	Age	Installed	Tank Material of Construction	Piping Material	Overfill Types
Tag Number Status	AST	Sump Tightness Inventory Control	Secondary Option Catastrophic L.D. Type 3.0	Secondary Option Piping Type	Spill Protected CP Met Types
Capacity		Line Tightness	ATG Type	Secondary Pipe Detection	Energy Act
6	17	4/1/1998	Steel Clad	Flexible Plastic	Flapper Valve (Auto Shutoff)
3617			Double-Walled	Double-Walled	Yes
Currently in Use			Not Required	Safe Suction	Not Applicable
Diesel			Continuous Interstitial Monitor	Deferred	
5,565					
7	17	4/1/1998	Steel Clad	Flexible Plastic	Flapper Valve (Auto Shutoff)
1135			Double-Walled	Double-Walled	Yes
Currently in Use			Not Required	Safe Suction	Not Applicable
Diesel			Continuous Interstitial Monitor	Deferred	
4,590					
8	17	4/1/1998	Steel Clad	Flexible Plastic	Flapper Valve (Auto Shutoff)
1136			Double-Walled	Double-Walled	Yes
Currently in Use			Not Required	Safe Suction	Not Applicable
Gasoline			Continuous Interstitial Monitor	Deferred	
2,365					
9	17	4/1/1998	Steel Clad	Flexible Plastic	Flapper Valve (Auto Shutoff)
1137			Double-Walled	Double-Walled	Yes
Currently in Use			Not Required	Safe Suction	Not Applicable
Gasoline			Continuous Interstitial Monitor	Deferred	
9,627					

Report Generation Date: 2/29/2016 Page 4

EKALAKA ELEMENTARY SCHOOL **Sys Fac ID:** 06-04710 Location:

106 E PARK ST Last Inspected On: 7/28/2015

EKALAKA, MT 59324 CARTER Operating Permit Renewal Date: 8/3/2018

Ed McBride, (406) 775-8767

PO BOX 458 (406)-775-8765 EKALAKA MT 59324-0458

Shay Beyer, UST Class A Operator

Owners/Operators: School Dist 15 Ekalaka Elementary, Owner

Contact:

Shay Beyer, UST Class B Global Operator

Tank Id	Age	Installed	Tank Material of Construction	Piping Material	Overfill Types
Tag Number	AST	Sump Tightness	Secondary Option	Secondary Option	Spill Protected
Status		Inventory Control	Catastrophic L.D. Type 3.0	Piping Type	CP Met Types
Product		Tank/Pipe CP	Tank Detection	Primary Pipe Detection	Vapor Recovery
Capacity		Line Tightness	ATG Type	Secondary Pipe Detection	Energy Act
2	24	8/1/1991	Cathodically Protected Steel	Flexible Plastic	Flapper Valve (Auto Shutoff)
859			Double-Walled	Double-Walled	Yes
Currently in Use			Not Required	U.S. Suction	Galvanic
Heating Oil		7/28/2015	Manual Interstitial Monitor	Manual Interstitial Monitor	
6,000					

Report Generation Date: 2/29/2016 Page 5